

FIG. 1




Fig. 1




Fig. 2




FIG. 3A




FIG. 3B

FIG. 4



440

FIG. 4






Fig. 5

105007 DTET0660



6A


SEM Micrograph of Group B at 300x after Electrochemical Test.




6B

SEM Micrograph of Group B at 700x after electrochemical test.

09501310-100501
T0500T-076T0560



7A




7B

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test indicates intergranular corrosion attacks.

70500T" 07E70660




7C




7D

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test exhibiting corrosion attacks.

105007" OFE0660



8A



8B

SEM micrographs of the Hayes CrCo sample prior to any corrosion test.